

IN THE CLAIMS:

1. (Currently Amended) A high pressure sensor mounting configuration comprising:

a cylindrical pressure sensor cavity comprising
a ~~convex~~ conical open end, and
a first bearing surface;

an internally threaded collet comprising a second bearing surface that bears on the first bearing surface when the internally threaded collet is threaded onto a pressure port, causing the ~~convex or concave~~ conical open end to bear on a ~~concave or convex~~ conical mating surface of the pressure port; and

a housing that captures the internally threaded collet on the cylindrical pressure sensor cavity.

2. (Currently Amended) The high pressure sensor mounting configuration according to claim 1, wherein the cylindrical pressure sensor cavity further comprises a flange to which the housing is affixed.

3. (Currently Amended) The high pressure sensor mounting configuration according to claim 1, wherein the first contact surface of the cylindrical pressure sensor cavity has first angle and the second contact surface of the internally threaded collet has a second angle that provide a line contact when the internally threaded collet is threaded onto the pressure port,

DOCKET NO.: ISD1348AP

and a third angle of the ~~convex-or-concave~~ conical open end provides a line contact to the ~~concave-or-convex~~ conical mating surface of the pressure port.

4. (Currently Amended) The high pressure sensor mounting configuration according to claim 3, wherein a clearance of the internally threaded collet to the cylindrical pressure sensor cavity and the first, second, and third angles are such as to allow a high pressure seal when the pressure sensor cavity is axially misaligned with the pressure port.

5. (Currently Amended) The high pressure sensor mounting configuration according to claim 1 wherein the housing is an electrical connector housing.

6. (Currently Amended) The high pressure sensor mounting configuration according to claim 1, wherein the cylindrical pressure sensor cavity has a groove that provides lateral stress relief to the cylindrical pressure sensor cavity.

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.